

**To:** scott.hansen@millelacsband.com[scott.hansen@millelacsband.com]  
**Cc:** Galbraith, Erin[galbraith.erin@epa.gov]  
**From:** Restaino, Mark  
**Sent:** Thur 4/25/2013 8:58:49 PM  
**Subject:** RE: Emailing: DOC137

Scott,

Are you available tomorrow?

We may need to get the attorney and Sherry involved with Mellen's.

-Mark

-----Original Message-----

From: Scott Hansen [mailto:Scott.Hansen@millelacsband.com]  
Sent: Thursday, April 25, 2013 3:47 PM  
To: Restaino, Mark  
Cc: Galbraith, Erin  
Subject: FW: Emailing: DOC137

Mark,

I stopped by Meleens for an inspection, no records could be located by the new manager Melissa Huff, to the best of her knowledge they were being sent to Erin. I inspected all the fills, sumps and three out of four of the dispensers. On dispenser 1, (attached photo) there was product leaking (premium) I had new manager come out and I showed her and said that it needed to be corrected ASAP.

I left a copy of the CP test and informed them to schedule a retest as required ASAP. I tested the top 9 inches of top soil and it appeared thawed.

They have an OPW 1500, and I can set up a three ring folder to help them Track tank tests by month. New manager was not familiar with system.

I stopped by Frederickson Marina and called his cell phone at 11:15 left a message about the need to inspect system by April 29, 2013.

I have not heard back.

Let's discuss.

Scott

Scott Hansen  
Environmental Program Manager  
Mille Lacs Band DNR/E  
(320) 532-7445 business  
(320) 532-7514 fax  
(320) 630 2439 cell

-----Original Message-----

From: Ryan Rupp  
Sent: Thursday, April 25, 2013 3:13 PM

To: Scott Hansen  
Subject: Emailing: DOC137

Your message is ready to be sent with the following file or link attachments:

DOC137

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.